

*Any tape found on strap is indication of a splice and should not be used for load containment. Dispose of taped section.